

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: YU et al.

Title: METHOD OF SIGNAL SUBSTITUTION FOR
MAINTENANCE OF AMPLIFIER SATURATION

Appl. No.: Unassigned

Filing Date: August 28, 2001

Examiner: Unassigned

Art Unit: Unassigned

TRANSMITTAL OF FORMAL DRAWINGS

Commissioner for Patents
Washington, D.C. 20231

ATTENTION: DRAWING REVIEW BRANCH

Sir:

Transmitted herewith are the formal drawings (11 sheets, Figures 1-10(b)) for the above-identified application. The Official Draftsperson is respectfully requested to approve these drawings for entry into the application.

Respectfully submitted,

Date

8/28/01

By

Johnny A. Kumar

FOLEY & LARDNER
Washington Harbour
3000 K Street, N.W., Suite 500
Washington, D.C. 20007-5109
Telephone: (202) 672-5489
Facsimile: (202) 672-5399

Johnny A. Kumar
Attorney for Applicant
Registration No. 34,649

Title: METHOD OF SIGNAL
SUBSTITUTION FOR MAINTENANCE
OF AMPLIFIER SATURATION

Inventor(s): YU et al.
DOCKET NO.: 033337-0117




FIG. 1(a)

Title: METHOD OF SIGNAL
SUBSTITUTION FOR MAINTENANCE
OF AMPLIFIER SATURATION

Inventor(s): YU et al.
DOCKET NO.: 033337-0117




FIG. 1(b)




FIG. 2

FIG. 2

Title: METHOD OF SIGNAL
SUBSTITUTION FOR MAINTENANCE
OF AMPLIFIER SATURATION

Inventor(s): YU et al.

DOCKET NO.: 033337-0117




FIG. 3

103220" E826E650




FIG. 4





FIG. 5

Title: METHOD OF SIGNAL
SUBSTITUTION FOR MAINTENANCE
OF AMPLIFIER SATURATION

Inventor(s): YU et al.
DOCKET NO.: 033337-0117



Title: METHOD OF SIGNAL
SUBSTITUTION FOR MAINTENANCE
OF AMPLIFIER SATURATION

Inventor(s): YU et al.
DOCKET NO.: 033337-0117




FIG. 7 (a)




FIG. 7 (b)

Title: METHOD OF SIGNAL
SUBSTITUTION FOR MAINTENANCE
OF AMPLIFIER SATURATION

Inventor(s): YU et al.
DOCKET NO.: 033337-0117




FIG. 8 (a)




FIG. 8 (b)

Title: METHOD OF SIGNAL
SUBSTITUTION FOR MAINTENANCE
OF AMPLIFIER SATURATION

Inventor(s): YU et al.
DOCKET NO.: 033337-0117




FIG. 9 (a)




FIG. 9 (b)

Title: METHOD OF SIGNAL
SUBSTITUTION FOR MAINTENANCE
OF AMPLIFIER SATURATION

Inventor(s): YU et al.
DOCKET NO.: 033337-0117




FIG. 10 (a)




FIG. 10 (b)